

SUPPLEMENTAL SERVICE INFORMATION

A6E560201034A01

- The following changes have been made since publication of the Mazda Automatic Transaxle Workshop Manual (1623-10-98E.).

AUTOMATIC TRANSAXLE DISASSEMBLY

- Oil pressure switch has been added.

ACCUMULATORS DISASSEMBLY/ASSEMBLY

- Spring specification has been modified.

CLUTCH COMPONENT DISASSEMBLY/ASSEMBLY

- Assembly procedure has been modified.

DIFFERENTIAL DISASSEMBLY/ASSEMBLY

- Conclusion type of differential ring gear has been added.
- Assembly procedure has been modified.

AUTOMATIC TRANSAXLE ASSEMBLY

- Oil pressure switch has been added.

AUTOMATIC TRANSAXLE INSPECTION

- 3-4 Clutch clearance has been modified.