

DTC U1900, U2012, U2523 [ABS]

B3E040243000W10

DTC	U1900, U2012, U2523	CAN line
DETECTION CONDITION	<ul style="list-style-type: none">• U1900, U2523<ul style="list-style-type: none">- Communication error with PCM is detected in CAN communication.• U2012<ul style="list-style-type: none">- CAN system wiring harness open or short circuit is detected.	
POSSIBLE CAUSE	<ul style="list-style-type: none">• CAN system wiring harness open or short circuit with PCM• PCM malfunction	

Diagnostic procedure

- Inspect according to diagnostic procedure in Section 09. (See [DTC TABLE \[MULTIPLEX COMMUNICATION SYSTEM\]](#).)