

## DTC U1900, U2012, U2023, U2202, U2523 [DSC]

---

B3E040243000W26

DTC	U1900, U2012, U2023, U2202, U2523	CAN line
DETECTION CONDITION	<ul style="list-style-type: none"><li>• U1900, U2023, U2202, U2523<ul style="list-style-type: none"><li>- Communication error with PCM is detected in CAN communication.</li></ul></li><li>• U2012<ul style="list-style-type: none"><li>- CAN system wiring harness open or short circuit is detected.</li></ul></li></ul>	
POSSIBLE CAUSE	<ul style="list-style-type: none"><li>• CAN system wiring harness open or short circuit with PCM</li><li>• PCM malfunction</li></ul>	

### Diagnostic procedure

- Inspect according to the diagnostic procedure in Section 09. (See [DTC TABLE \[MULTIPLEX COMMUNICATION SYSTEM\]](#).)