

## NO.19 EXCESSIVE SHIFT SHOCK ON TORQUE CONVERTER CLUTCH (TCC)

---

B3E050319090W23

<b>19</b>	<b>Excessive shift shock on torque converter clutch (TCC)</b>
<b>DESCRIPTION</b>	• Strong shock is felt when the TCC is engaged.
<b>POSSIBLE CAUSE</b>	• The troubleshooting flow is the same as No.16 "Judder upon TCC operation".