

DTC C1099

B3E060201038W08

DTC	C1099	Electric power steering oil pump (motor)
DETECTION CONDITION	• The EHPAS control module detects that the motor speed is less than the specified value.	
POSSIBLE CAUSE	• Motor internal malfunction	

Diagnostic procedure

STEP	INSPECTION	ACTION	
1	REPLACE ELECTRIC POWER STEERING OIL PUMP • Replace the electric power steering oil pump, then go to the next step. (See ELECTRIC POWER STEERING OIL PUMP (LF) REMOVAL/INSTALLATION.)		
2	VERIFY THAT NO OTHER DTCS ARE PRESENT • Are any other DTCs output?	Yes	Go to the applicable DTC inspection. (See DTC Table.)
		No	DTC troubleshooting completed.