

- [!\[\]\(1207edb9a08751d3d55970560645ed23\_img.jpg\) ABS SYSTEM WIRING DIAGRAM](#)
- [!\[\]\(d7a34a706cfa4ef37c62a369101e1b36\_img.jpg\) ON-BOARD DIAGNOSIS \[ABS\]](#)
- [!\[\]\(7325769475e8f4bf67f57a0cbebc8ab9\_img.jpg\) DTC B1317, B1318 \[ABS\]](#)
- [!\[\]\(1a468f12cdfc63dc07896d0781cf55ec\_img.jpg\) DTC B1342, C1267 \[ABS\]](#)
- [!\[\]\(a9a0baec8ceb7d7c04180806eca8d32a\_img.jpg\) DTC C1095 \[ABS\]](#)
- [!\[\]\(c1ab807d6aebb565b3082513037b5622\_img.jpg\) DTC C1141, C1142, C1143, C1144, C1233, C1234, C1235, C1236 \[ABS\]](#)
- [!\[\]\(083bb479299cb5e55cd99db0433ca6ba\_img.jpg\) DTC C1145, C1155, C1165, C1175 \[ABS\]](#)
- [!\[\]\(ede41f318336daae6cce8449321d11ea\_img.jpg\) DTC C1446 \[ABS\]](#)
- [!\[\]\(b0cd9d88e5935e4c3891570bfdded05c\_img.jpg\) DTC U1900, U2012, U2523 \[ABS\]](#)