

- [!\[\]\(1207edb9a08751d3d55970560645ed23_img.jpg\) FOREWORD](#)
- [!\[\]\(d7a34a706cfa4ef37c62a369101e1b36_img.jpg\) AIR BAG SYSTEM WIRING DIAGRAM \(ON-BOARD DIAGNOSTIC\)](#)
- [!\[\]\(7325769475e8f4bf67f57a0cbebc8ab9_img.jpg\) DTC DISPLAY](#)
- [!\[\]\(1a468f12cdfc63dc07896d0781cf55ec_img.jpg\) CLEARING DTC](#)
- [!\[\]\(a9a0baec8ceb7d7c04180806eca8d32a_img.jpg\) DTC TABLE](#)
- [!\[\]\(c1ab807d6aebb565b3082513037b5622_img.jpg\) PID/DATA MONITOR DISPLAY](#)
- [!\[\]\(083bb479299cb5e55cd99db0433ca6ba_img.jpg\) PID/DATA MONITOR TABLE](#)
- [!\[\]\(ede41f318336daae6cce8449321d11ea_img.jpg\) DTC B1046, B2773, B2774, B2775, B2776](#)
- [!\[\]\(b0cd9d88e5935e4c3891570bfdded05c_img.jpg\) DTC B1047, B1992, B1993, B1994, B1995](#)
- [!\[\]\(81bb4e52f43acc06353225c332f66031_img.jpg\) DTC B1048, B1925, B1933, B1935, B1938](#)
- [!\[\]\(4862a3d83a50b6aa02d9ef677ec36116_img.jpg\) DTC B1049, B1881, B1882, B1883, B1886](#)
- [!\[\]\(b564abb3972f4216a833af91832e1619_img.jpg\) DTC B104B, B104E, B1051, U2017](#)
- [!\[\]\(3e91863309aa91e589b5ab92c8ebd53f_img.jpg\) DTC B104C, B104F, B1050, U2018](#)
- [!\[\]\(bf6def3f21dfdb4b0473718404626f2c_img.jpg\) DTC B104D, B2226, B2227, B2855](#)
- [!\[\]\(b0485233f98b941f2381b77fe3b6686f_img.jpg\) DTC B1053, B2432, B2433, B2434, B2435](#)
- [!\[\]\(fd5c36680d4471e605732b36788643ca_img.jpg\) DTC B1054, B1877, B1878, B1879, B1885](#)
- [!\[\]\(cfcb6e3fe14cf2366208370376c5c0f9_img.jpg\) DTC B1055, B1996, B1997, B1998, B1999](#)
- [!\[\]\(17fbea93b96fb691279feb16b3dfba47_img.jpg\) DTC B1056, B2777, B2778, B2779, B2780](#)
- [!\[\]\(c943c40aac9d4dd9481d8d4b932db11b_img.jpg\) DTC B1057, B1916, B1932, B1934, B1936](#)
- [!\[\]\(78722dd8a40b4b8cba6c4bc2496af0ff_img.jpg\) DTC B1058, B2228, B2230, B2232, B2234](#)
- [!\[\]\(7ca57550f01dd657cd5fb0b4b39070e5_img.jpg\) DTC B1059, B2229, B2231, B2233, B2235](#)
- [!\[\]\(27d08d42762e05345080235dfb8fd4f5_img.jpg\) DTC B105A](#)
- [!\[\]\(a0120eed5345e3ef041f32d510bbaaa4_img.jpg\) DTC B1231](#)
- [!\[\]\(5d135eaf0db5ba5bb50522e31d409887_img.jpg\) DTC B1317, B1318](#)
- [!\[\]\(999a3b623d1b2e259ce371a576a89b57_img.jpg\) DTC B1342](#)
- [!\[\]\(b6fcbc36e74bb8f6df2b3fdc5d230a1a_img.jpg\) DTC B1884, B1890](#)
- [!\[\]\(32a22410411096e2c8d32731f78c9ccc_img.jpg\) DTC B1921](#)
- [!\[\]\(c0c9b82c73e1cc6d7e87bf54578e2a82_img.jpg\) DTC B2477](#)
- [!\[\]\(3a6ac41b3f099dd17a52d14a1994c5e3_img.jpg\) DTC B2856, B2886, B2887](#)
- [!\[\]\(d8728fc7d0d18b43bb799e0b75e28476_img.jpg\) SYMPTOM TROUBLESHOOTING](#)
- [!\[\]\(70bb55f7aa836a2ee4c67662da4967eb_img.jpg\) AIR BAG SYSTEM](#)
- [!\[\]\(b2232297cce97c56f57b421760817d12_img.jpg\) NO.1 AIR BAG SYSTEM WARNING LIGHT DOES NOT ILLUMINATE](#)
- [!\[\]\(55709881e7481dfc15adc40dcd59becf_img.jpg\) NO.2 AIR BAG SYSTEM WARNING LIGHT ILLUMINATES CONSTANTLY](#)