

## NO.16 HIGH OIL CONSUMPTION/LEAKAGE [LF]

B3E010318881W18

<b>16</b>	<b>HIGH OIL CONSUMPTION/LEAKAGE</b>
<b>DESCRIPTION</b>	Oil consumption is excessive.
<b>POSSIBLE CAUSE</b>	<ul style="list-style-type: none"> <li>• PCV valve malfunction</li> <li>• Improper dipstick</li> <li>• Improper engine oil viscosity</li> <li>• Engine internal parts malfunction</li> </ul>

### Diagnostic procedure

STEP	INSPECTION	RESULTS	ACTION
1	Remove and shake the PCV valve. Does the PCV valve rattle?	Yes	Go to the next step.
		No	Replace the PCV valve.
2	Inspect for following: • External leakage • Proper dipstick • Proper engine oil viscosity Are all items normal?	Yes	Inspect the internal engine parts such as valves, valve guides, valve stem seals, cylinder head drain passage, and piston rings.
		No	Service if necessary. Repeat Step 2.
3	Verify test results. • If normal, return to diagnostic index to service any additional symptoms. (See <a href="#">ENGINE SYMPTOM TROUBLESHOOTING [LF]</a> .) • If malfunction remains, inspect related Service information perform repair or diagnosis.  - If vehicle repaired, troubleshooting completed. - If vehicle not repaired or additional diagnostic information not available, replace the PCM. (See <a href="#">PCM REMOVAL/INSTALLATION [LF]</a> .)		