

# INSPECTION AFTER TRANSAXLE OVERHAUL [G35M-R]

---

B3E051501029W08

1. After warming up the engine, drive the vehicle and inspect the following items:

- (1) No abnormal noise in each shift position.
- (2) Smooth shift operation when shifting gears.
- (3) No gear slipout after shifting gears.
- (4) Back-up light switch operates correctly.