

DTC B1342

B3E060201038W05

DTC	B1342	EHPAS control module
DETECTION CONDITION	• The EHPAS control module on-board diagnostic function detects system malfunction.	
POSSIBLE CAUSE	<ul style="list-style-type: none"> • EHPAS control module internal malfunction • Poor connection at connectors 	

Diagnostic procedure

STEP	INSPECTION	ACTION
1	VERIFY THAT THE SAME DTC IS NOT PRESENT <ul style="list-style-type: none"> • Clear the DTC from the memory. (See Clearing DTCs Procedure.) • Is the same DTC present? 	Yes Replace the electric power steering oil pump, then go to the next step. (See ELECTRIC POWER STEERING OIL PUMP (LF) REMOVAL/INSTALLATION.)
		No Go to the next step.
2	VERIFY THAT NO OTHER DTCS ARE PRESENT <ul style="list-style-type: none"> • Are any other DTCs output? 	Yes Go to the applicable DTC inspection. (See DTC Table.)
		No DTC troubleshooting completed.