

DTC B1251, B1253, B1274, B1275, B1282, B1283, B1947, B2014 (MULTIPLE DTCS INDICATED)

B3E070201038W03

DTC B1251, B1253, B1947, B2014, B1282, B1283, B1274, B1275	Climate control unit (+5 V power supply or sensor ground) system
POSSIBLE CAUSE	• Open circuit in wiring harnesses between climate control unit and each temperature sensor, air mix actuator, or airflow mode actuator

Diagnostic Procedure

STEP	INSPECTION	ACTION
1	<ul style="list-style-type: none"> Disconnect the climate control unit connector and the evaporator temperature sensor connector. Is there an open circuit in the wiring harness between climate control unit terminal U and evaporator temperature sensor terminal A? 	Yes
		Repair the wiring harness.
		No
		The system is normal at present. (Clear the past malfunction from the memory.)

<p>CLIMATE CONTROL UNIT CONNECTOR</p>	<p>EVAPORATOR TEMPERATURE SENSOR CONNECTOR</p>
---------------------------------------	--