

DTC B2477

B3E090201072W40

DTC B2477	Module configuration failure
DETECTION CONDITION	PJB data configuration error
POSSIBLE CAUSE	<ul style="list-style-type: none"> • Configuration has not been completed. • PJB malfunction

Diagnostic procedure

STEP	INSPECTION	ACTION
1	INSPECT DTC <ul style="list-style-type: none"> • Clear the DTC from the PJB memory using the WDS or equivalent. • Perform the self-test. (See PJB SELF-TEST.) • Is the same DTC present? 	Yes Perform PJB configuration procedure. (See PASSENGER JUNCTION BOX (PJB) CONFIGURATION.) Go to the next step.
		No Go to the next step.
2	VERIFY TROUBLESHOOTING COMPLETED <ul style="list-style-type: none"> • Make sure to reconnect all disconnected connectors. • Clear the DTC from the PJB memory using the WDS or equivalent. • Perform the self-test. (See PJB SELF-TEST.) • Is the same DTC present? 	Yes Replace the PJB. (See PASSENGER JUNCTION BOX (PJB) REMOVAL/INSTALLATION.)
		No DTC troubleshooting completed.