

DTC 09:ER22

B3E090266900W05

DTC 09:Er22	Base unit (peripheral circuit for tuner)
DETECTION CONDITION	• Base unit detects malfunction in inner circuit (related to tuner).
POSSIBLE CAUSE	• Base unit malfunction

Diagnostic procedure

INSPECTION		ACTION
Clear the DTC and operate the radio for 3 s or more . Is DTC 09: Er22 indicated?	Yes	Replace the base unit.
	No	DTC troubleshooting completed.