


TRUNK LID STAY DAMPER DISPOSAL

B3E091056930W01

Note

- The gas in the stay damper is colorless, odorless, and non-toxic.

1. Wear protective eye wear.
2. Lay the stay damper flat.



3. Saw **2-3 mm {0.08-0.11 in}** into the stay damper using a hacksaw, and allow the gas to escape from the stay damper.
4. Verify that the gas has escaped from the stay damper.
5. Discard the stay damper.