


SEAT WARMER SWITCH INSPECTION

B3E091388110W02

1. Verify that the continuity between the seat warmer switch terminals is as indicated in the table.



- If not as indicated in the table, replace the seat warmer switch.

Switch position	Terminal				
	C	A	D	E	F
On	○—○	○—○	○—○	○—○	○—○
Off	○—○	○—○	○—○	○—○	○—○

○—○ : Continuity ○—○ : Bulb

B3E0913W 110