


## FRONT ANTENNA FEEDER INSPECTION

B3E092066940W02

1. Verify that there is no continuity between the front antenna feeder terminal A and B.
2. Verify that the continuity is as indicated in the table.



- If not as indicated in the table, replace the front antenna feeder.

Step	Terminal			
	A	B	C	D
1	○	—	○	
2		○	—	○

○—○ : Continuity

CHU0920W019