


DATA MONITORING AND RECORDING PROCEDURE

B3E092255430W06

1. Connect the WDS or equivalent to the diagnostic connector 2 (16-pin).



2. Verify the data monitor items.

Indication Item Table

Monitor item	Input-output signal/part name	Unit/State		Terminal
CCNT_HE	DTC	Number of continuous DTCs		-
ECT_GAUGE	Water temperature gauge	°F	°C	1I, 1K
NUMKEYS	Number of key ID numbers registered with the vehicle	-		-
ODO COUNT	Odometer	m		1I, 1K
RPM	Tachometer	rpm		
SPEEDSG	Speedometer	mph	km/h	