

- [!\[\]\(1207edb9a08751d3d55970560645ed23\_img.jpg\) MULTIPLEX COMMUNICATION SYSTEM](#)
- [!\[\]\(d7a34a706cfa4ef37c62a369101e1b36\_img.jpg\) DTC TABLE \[MULTIPLEX COMMUNICATION SYSTEM\]](#)
- [!\[\]\(7325769475e8f4bf67f57a0cbebc8ab9\_img.jpg\) PROCEDURES FOR DETERMINING THE LOCATION OF A MALFUNCTION](#)
- [!\[\]\(1a468f12cdfc63dc07896d0781cf55ec\_img.jpg\) DTC U0073, U2012](#)
- [!\[\]\(a9a0baec8ceb7d7c04180806eca8d32a\_img.jpg\) DTC U0073, U0516, U1900, U2516](#)