

- [!\[\]\(1207edb9a08751d3d55970560645ed23_img.jpg\) DTC INSPECTION](#)
- [!\[\]\(d7a34a706cfa4ef37c62a369101e1b36_img.jpg\) DTC B1251, B1253](#)
- [!\[\]\(7325769475e8f4bf67f57a0cbebc8ab9_img.jpg\) DTC B1251, B1253, B1274, B1275, B1282, B1283, B1947, B2014 \(MULTIPLE DTCS INDICATED\)](#)
- [!\[\]\(1a468f12cdfc63dc07896d0781cf55ec_img.jpg\) DTC B1260, B1261](#)
- [!\[\]\(a9a0baec8ceb7d7c04180806eca8d32a_img.jpg\) DTC B1260, B1261, B1274, B1275, B1282, B1283 \(MULTIPLE DTCS INDICATED\)](#)
- [!\[\]\(c1ab807d6aebb565b3082513037b5622_img.jpg\) DTC B1274, B1275](#)
- [!\[\]\(083bb479299cb5e55cd99db0433ca6ba_img.jpg\) DTC B1282, B1283](#)
- [!\[\]\(ede41f318336daae6cce8449321d11ea_img.jpg\) DTC B1947, B2014](#)
- [!\[\]\(b0cd9d88e5935e4c3891570bfdded05c_img.jpg\) DTC B2832](#)
- [!\[\]\(81bb4e52f43acc06353225c332f66031_img.jpg\) DTC B2834](#)
- [!\[\]\(4862a3d83a50b6aa02d9ef677ec36116_img.jpg\) FOREWORD](#)
- [!\[\]\(b564abb3972f4216a833af91832e1619_img.jpg\) TROUBLESHOOTING INDEX](#)
- [!\[\]\(3e91863309aa91e589b5ab92c8ebd53f_img.jpg\) NO.1 INSUFFICIENT AIR \(OR NO AIR\) BLOWN FROM VENTS](#)
- [!\[\]\(bf6def3f21dfdb4b0473718404626f2c_img.jpg\) NO.2 AMOUNT OF AIR BLOWN FROM VENTS DOES NOT CHANGE](#)
- [!\[\]\(b0485233f98b941f2381b77fe3b6686f_img.jpg\) NO.3 AMOUNT OF AIR BLOWN FROM VENTS DOES NOT CHANGE](#)
- [!\[\]\(fd5c36680d4471e605732b36788643ca_img.jpg\) NO.4 AIR INTAKE MODE DOES NOT CHANGE](#)
- [!\[\]\(cfcb6e3fe14cf2366208370376c5c0f9_img.jpg\) NO.5 NO TEMPERATURE CONTROL WITH CLIMATE CONTROL UNIT](#)
- [!\[\]\(17fbea93b96fb691279feb16b3dfba47_img.jpg\) NO.6 WINDSHIELD FOGGED](#)
- [!\[\]\(c943c40aac9d4dd9481d8d4b932db11b_img.jpg\) NO.7 AIR FROM VENTS NOT COLD ENOUGH](#)
- [!\[\]\(78722dd8a40b4b8cba6c4bc2496af0ff_img.jpg\) NO.8 NO COOL AIR](#)
- [!\[\]\(7ca57550f01dd657cd5fb0b4b39070e5_img.jpg\) NO.9 NOISE WHILE OPERATING A/C SYSTEM](#)