

DTC B1342 [IMMOBILIZER SYSTEM]

B3E090201077W16

DTC: B1342	Instrument cluster malfunction
DETECTION CONDITION	• Instrument cluster malfunction
POSSIBLE CAUSE	• Instrument cluster malfunction

Diagnostic Procedure

STEP	INSPECTION		ACTION
1	EXAMINE INSTRUMENT CLUSTER AND PCM • Is the DTC displayed? - WDS or equivalent: B1342	Yes	Replace the instrument cluster and perform the resetting procedure for the immobilizer system when replacing the instrument cluster. (See INSTRUMENT CLUSTER REMOVAL/INSTALLATION.) (See IMMOBILIZER SYSTEM COMPONENT REPLACEMENT/KEY ADDITION AND CLEARING.)
		No	DTC troubleshooting completed.