


## SUNROOF SWITCH INSPECTION

B3E091566560W02

1. Verify that the continuity between the sunroof switch terminals is as indicated in the table.



- If not as indicated in the table, replace the sunroof switch.

Switch position	Terminal				
	A	D	F	H	G
Slide open		○		○	○
Slide close			○	○	○
Tilt up				○	○
Tilt down	○				○
OFF					

○ — ○ : Continuity

B3E0915W 112