


## CENTER ROOF ANTENNA INSPECTION

B3E092066931W02

1. Verify that there is no continuity between the center roof antenna terminals A and C using an ohmmeter.



2. Inspect for continuity between the center roof antenna terminals using an ohmmeter.

- If not as indicated in the table, replace the center roof antenna.

○—○: Continuity		
Test condition	Terminal	
	A	B
Under any condition	○	○

A6E8 124W031