


BACK-UP LIGHT SWITCH INSPECTION

B3E091817640W02

1. Verify that the continuity between the back-up light switch terminals is as indicated in the table.



- If not as indicated in the table, replace the back-up light switch.

Shift lever position	Terminal	
	A	B
Reverse	○ — ○ : Continuity	
Except above		

B3E0919W164